


# IMPORTANT SAFETY NOTICE

## RECALL OF HOMELITE BACKPACK BLOWER

### MODELS UT08580 AND UT08580A

Sold Before October 16, 2009



Some Homelite backpack blowers sold prior to October 16, 2009 may be equipped with fuel tanks that can leak gasoline posing a potential fire hazard to the consumer. If you purchased a Homelite backpack blower model # UT08580 or UT08580A before October 16, 2009 the fuel tank may leak gasoline. Please immediately discontinue use of the product and contact Homelite Customer Service at 1-800-242-4672 to obtain the location of your nearest Homelite authorized service center. The authorized service center will replace the fuel tank free of charge.

Affected products are limited to those with manufacture dates between July 1, 2007 and June 23, 2009. The model number and date of manufacture are included on the product's data label located on the red plastic housing above the choke knob and adjacent to the fuel tank as illustrated in the above examples. Products with the letters "CA" embossed on the fuel tank or a green "dot" on the outside of the package are not affected products.

**If you have any questions or require additional information, please contact Homelite Consumer Products, Inc. at 1-800-242-4672 or visit [www.homelite.com](http://www.homelite.com).**